

## **Motorable Road to Amarnath Cave Shrine**

#### Source: IE

### Why in News?

The <u>Border Roads Organisation (BRO)</u> has completed the construction of a motorable road that connects the <u>Amarnath cave shrine</u> in Kashmir's Lidder Valley with **the Baltal base camp**, making the pilgrimage more accessible and comfortable for the devotees.

 This milestone resulted from the successful upgrade of the Baltal road, a feat accomplished through the continuous efforts of Project Beacon.

#### Note:

- Project Beacon is the BRO's oldest undertaking, was raised on May 18, 1960, with its headquarters at Srinagar, Jammu and Kashmir.
  - Beacon currently takes care of the road infrastructure development and maintenance in important areas of Kashmir.

# What are the Key Facts Regarding Amarnath Cave Shrine?

- The Amarnath mountain features a cave on its south famously known as the Amarnath Cave. This cave is the location of the Amarnath Temple, a significant Hindu shrine situated in the Pahalgam tehsil of the Anantnag district in Jammu and Kashmir, India.
  - The shrine is perched at an altitude of 3,800 metres, contributing to the challenging nature of the pilgrimage.
- **Amarnath Peak**, a part of the **Himalayas** is a mountain with a peak elevation of 5,186 meters, in the Ganderbal district of Jammu and Kashmir, in the vicinity of Sonamarg.
- Amarnath yatra is an annual pilgrimage to the Amarnath cave, where devotees pay homage to an ice stalagmite believed to be the lingam of Lord Shiva.
  - The ice stalagmite forms every year during **the summer months** and reaches its maximum size in July and August, when thousands of Hindu devotees make an annual pilgrimage to the cave.
- Traditional Access Routes:
  - Pilgrims historically approached the shrine via two routes Pahalgam and Sonamarg both located in the Lidder Valley, each presenting its own set of challenges through demanding terrains.
  - Pilgrims also had the option to use chopper services from Baltal to Panchtarni, located 6 km away from the shrine. However, ecological concerns led to the discontinuation of services directly to the shrine.



